EXHIBIT 4

February 26 2016 NHTSA ID Number: 10838539

Components: POWER TRAIN

NHTSA ID Number 10838539

Incident Date February 26 2016

Consumer Location DALLAS, TX

Vehicle Identification Number 1C6RR7PM1FS******

Complaint Summary

0

CRASH No FIRE No INJURIES 0

DEATHS

THE VM MOTOR HAS NUMEROUS FAILURES RESULTING FROM THE CAMSHAFT GEAR ON THE FUEL PUMP SIDE OF THE MOTOR SLIPPING AND CAUSING CATASTROPHIC ENGINE FAILURE. THESE PROBLEMS WILL OCCUR GENERALLY AFTER 70K MILES. THERE IS A PROCESS CURRENTLY PERFORMED BY D&J DIESEL IN MIDVALE UTAH TO PERMANENTLY FIX THIS PROBLEM. ECODIESEL OWNERS PAID A PREMIUM FOR THE DIESEL UPGRADE SINCE DIESEL MOTORS ARE RENOWN FOR THEIR LONGEVITY. THIS ACHILLES HEAL MARRING THE RELIABILITY AND CAUSING AN UNSAFE TIME BOMB SHOULD HAVE BEEN ADDRESSED BY THE MANUFACTURER TO RECALL THE VEHICLES. THUS FAR RAM HAS NOT TAKEN ACTION. ATTACHED ARE A FEW LINKS DESCRIBING FAILURES.

HTTP://WWW.PIRATE4X4.COM/FORUM/GENERAL-CHIT-CHAT/2242010-REAL-WORLD-ECODIESEL-RELIABILITY-SO-FAR-4.HTML

HTTP://WWW.ECODIESELRAM.COM/FORUM/THREADS/ENGINE-FAILURE-148000-MILES.478/

HTTP://WWW.RAM1500DIESEL.COM/FORUM/RAM-1500-DIESEL-GENERAL-DISCUSSION/5710-MY-DEALER-HAS-2-BLOWN-ECODIESEL-TRUCKS-2.HTML

HTTP://WWW.RAM1500DIESEL.COM/FORUM/RAM-1500-DIESEL-MECHANICAL/8564-ECO-DIESEL-ENGINE-FAILURES.HTML

HTTP://WWW.RAM1500DIESEL.COM/FORUM/RAM-1500-DIESEL-MECHANICAL/7275-2014-RAM-LOUD-TICKING-NOISE-ENGINE-MAYBE-CAMSHAFT-BEARING-FAILURE.HTML

HTTP://WWW.RAM1500DIESEL.COM/FORUM/RAM-1500-DIESEL-GENERAL-DISCUSSION/2833-ENGINE-BLEW-UP-23.HTML

Affected Products (1)

Vehicle

WODEL TENT	MAKE MOI	DEL	YEAR
------------	----------	-----	------

RAM	1500	2015
10 1101	1000	2010

January 29 2017 NHTSA ID Number: 10948341 Components: FUEL/PROPULSION SYSTEM

NHTSA ID Number 10948341

Incident Date January 19 2017

Consumer Location PEYTON, CO

Vehicle Identification Number 1C4RJFBMXEC******

Complaint Summary

0

CRASH NO SERVICE DEF CAME ON AT 34,000 MILES. DEALER SAID THAT THE DEF
WAS CONTAMINATED WITH CRYSTALS AND THE PUMP NEEDED

FIRE No REPLACED. REFUSED TO COVER IT UNDER WARRANTY DUE TO

INJURIES 0 CONTAMINATION. ONLY PEAK BLUE DEF WHICH MEETS ISO 22241 HAS

BEEN USED IN THE VEHICLE. DEALERSHIP THEN TOLD US TO DRIVE THE

VEHICLE UNTIL THE BACK ORDERED PART WAS AVAILABLE. WHEN

QUERIED ABOUT THE VEHICLE GOING INTO "LIMP MODE" THEY AGREED IT WAS A POSSIBILITY. THEY WOULD NOT PROVIDE A LOANER VEHICLE UNTIL THE PART ARRIVED AND WILL NOT COVER UNDER WARRANTY. THERE ARE HUNDREDS OF CASES ON JEEP FORUMS WITH THE SAME ISSUE. IT IS A SAFETY ISSUE IF A DEALER TELLS YOU TO DRIVE A VEHICLE

ISSUE. IT IS A SAFETY ISSUE IF A DEALER TELLS YOU TO DRIVE A VEHICLE THEY KNOW WILL GO INTO LIMP MODE, ESPECIALLLY ON A FREEWAY. WE ALSO HAVE A 14 MONTH OLD CHILD AND LIVE IN COLORADO, BREAKING DOWN ON THE SIDE OF THE ROAD IS NOT AN OPTION. THE DEALER DOES

NOT RETURN PHONE CALLS AND CHRYSLER CUSTOMER CARE SIDED

WITH THE DEALER AND PROVIDED NO ASSISTANCE.

Affected Products (1)

Vehicle

DEATHS

MAKE	MODEL	YEAR
JEEP	GRAND CHEROKEE	2014

July 06 2017 NHTSA ID Number: 11003301

Components: FUEL/PROPULSION SYSTEM

NHTSA ID Number 11003301

Incident Date June 29 2017

Consumer Location AUSTIN, TX

Vehicle Identification Number 1C6RR6LT9ES******

Complaint Summary

CRASH NO CHECK ENGINE LIGHT ON WITH FUEL SYSTEM ERROR WARNING. HAD TO

FIRE No REPLACE FULE PUMP ASSEMBLY.

INJURIES 0

DEATHS 0

Affected Products (1)

Vehicle

MAKE	MODEL	YEAR
RAM	1500	2014

November 30 2017 NHTSA ID Number: 11051571 Components: FUEL/PROPULSION SYSTEM

NHTSA ID Number 11051571

Incident Date November 19 2017

Consumer Location TRUMBULL, CT

Vehicle Identification Number 1C6RR7NM9GS******

Complaint Summary

CRASH No TRUCK SHUTDOWN WHILE DRIVING DOWN HIGHWAY @ 65 MPH WITHOUT

FIRE No ANY OTHER SYMPTOMS. HAD TO COAST TO SIDE OF BUSY ROAD.

SERVICE ELECTRONIC THROTTLE CONTROL FLASHED AS WELL AS THE CHECK ENGINE LIGHT. THE TRUCK NEVER STUTTERED OR LOST ANY

DEATHS 0 POWER PRIOR TO THIS. DEALERSHIP STATES THAT IT IS BAD DIESEL

FUEL. REPLACED HPFP BUT TRUCK WILL STILL NOT START. CHRYSLER HAS INSTRUCTED DEALER TO REPLACE ENTIRE FUEL SYSTEM. THIS HAS NOT BEEN DONE YET BECAUSE CHRYSLER WILL NOT WARRANTY EVEN

THOUGH THE TRUCK IS STILL UNDER WARRANTY.

Affected Products (1)

Vehicle

MAKE	MODEL	YEAR
RAM	1500	2016